

GENERAL INSTRUCTION FOR 6.35/11(12) kV STRAIGHT JOINTS,
 THREE CORE POLYMERIC CABLES,
 WITH COPPER TAPE SCREENS WITH ARMOUR.

Серия **SERIES: H3C-11E**

Kit <i>КОМПЛЕКТ</i>	<i>диаметр с учетом изоляции</i> Diameter over insulation mm мм	<i>сечение</i> Cross section mm ²	<i>диаметр с учетом соединителя</i> Diameter over connector mm	<i>длина соединителя</i> Connector length max mm	<i>масс. в мм</i>
H3C9511E, H3C18511E H3C24011E H3C30011F	19-30	95-240	30	135	
	23-44	300	33	180	

General Instructions:**VERY IMPORTANT PLEASE READ BEFORE STARTING TO JOINT.**

Before shrinking one tube onto another or onto polymeric insulation or before applying any mastic, clean and degrease the underlying surfaces. Where any of these surfaces are semi conducting or stress controlling take care not to drag any carbon particles onto any insulating components. Metal sheaths of cables should always be scraped /abraded and degreased before applying any earth bonds or mastics. Plastic cable sheaths should be abraded and degreased for at least 100 mm beyond the sheath cut as this area forms the primary external water seal.

The reliability of the jointing system relies on cleanliness and dimensional accuracy, always check the stripping diagram and keep the joint assembly as clean as possible.

Overlap the cores by at least 100 mm.

Mark the centre line of the connection on all cables. DO NOT cut the cores to length until you have established whether you need to cross cores!

After fitting; tap all roll springs with a light hammer or similar instrument and 'hand tighten' by manually rolling the spring.

Protect all roll springs with a few turns of No 23 tape, applies in the direction of the roll; this prevents resin penetrating the spring and isolating any earth connection.

Fitting ferules; for compression connectors; measure the length of the connector and remove the insulation for half the connector length plus 5 mm. For water blocked connectors measure the depth of barrel plus 5 mm from the insulation removal position and cut off any excess conductor.

NB; THE JOINT BODIES ARE DESIGNED FOR SYMMETRICAL APPLICATION EITHER SIDE OF THE CENTRE LINE OF THE FERULE.

Before stripping the cable cores; set the cores, including any cross, and mark the centre line on all cores. All screen cuts should be measured from these marks.

REF. DIMN.	95-240mm ²	300mm ²
A	170	200
B	250	250
C	735	760
D	650	730

кабели заземления

DRAIN WIRE TYPE CABLE


неговите проводници
Copper wires

заземлюющая оболочка
Abrade sheath of all polymeric
cables for at least 100 mm
beyond sheath cut

Insulation removal see note
under general instructions
Устранение изоляции: см. общие
указания по удалению изоляции

кабели IEC


IEC TYPE CABLE



- Arrange the cables for jointing.
- Set the cores and check the distance between sheath cuts matches the sum of the strip lengths
- Mark the connection centre line on all cable cores and strip the cables as shown on the stripping diagram.


If the cable does not have any copper wires you must use the separate earth bonding kit with copper braids and roll springs to bond the copper tapes to the armours.

1





- Remove the sheath.
- Remove the armours leaving a wire binder in place.
- Remove the bedding.
- Remove any fillers.
- Fold the copper wires back without over bending them and tape them to the sheath, do not cut to length yet.
- Remove the copper tape screen and bind the end with a few turns of EPR tape.
- Remove the semi-conducting screen.
- REMOVING THE INSULATION FOR FITTING THE CONNECTOR.**

For compression connectors remove the insulation for half the connector, (a), length plus 5 mm.



- a) Slide the two outer protection tubes over the cables.
b) Slide stocking braid over the core to be connected.
c) Park the joint body on the first core to be connected; (long side of joint) crossed core should be jointed first, with the crossing done on the short side of the joint.
- 3** Note: joint body should be fitted with blue 'Velcro' straps facing towards long side of joint



расчётный тип крестообразной


'C' SPANNER
TWO OFF

H3C-11E-JIE ISSUE 1 FEB 06


соед. части равновесная со всех
Joint body equal either *сторон от центра*
side of the connector *соединительной*
centre when recovered. *шпунт в исходном*
положении.

обмотать до верха
сумки соединительной

EPR tape up to the top of taper of joint body



- Complete one core at a time, starting with the crossed core.
- Fit the connector equally either side of the centre line of the joint; follow the compression sequence shown above.
- Clean the cores to be jointed leave the connector until last.
- Mark on the core screen two positions on the short side of the joint.
 - See table below for landing position, 'X'
 - From the above landing guide mark a second position equal to the distance the plastic carrier is protruding from the moulding, 'Y'







POSITION	Толщина
X	95-300mm ² 20mm

- Place the joint body in place over the connector, end of the plastic carrier should be positioned over guide position 'Y'.
- Fit the two 'C' spanners in the slots of the body. These should be positioned so as when held, the jointer can push one spanner and pull the other.
- With one twisting movement 'Break' the carrier of the body. Approximately 1/3 of the body will shrink down onto the core, check that the end of the moulding is positioned at 'X' (adjust if necessary)
- Release the Velcro strips to allow the remaining joint body to shrink down. (recheck dimensions).
- Remove the two carriers, which have now been released onto the cores. This can best be achieved by tapping with a hammer.
- Apply 3 half lap layers of EPR tape with 50% stretch commencing 10mm onto the core screen and terminating at the end of the taper on the joint body.

PTO.

- k) Position the stocking braid centrally over the joint body. Fold down the ends onto the copper tape screen and secure using the constant force springs supplied.
- l) Over-tape the spring with a few turns of EPR tape. (NB: tape to be applied in the same direction as the spring)
- m) Complete the other connections

4



защитная оболочка
из ПВХ
PVC SERVING



первичные лепесточные клипсы для
соединения заземляющего экрана с армированной
Worm drive clips to connect earth screen to
armour.


EPR tape

каучуковая
лента

EPR tape
каучуковая лента

NB:- Place PVC SERVING onto head of worm clip
prior to taping over as indicated above.


Примечание: Поместите защитную оболочку из ПВХ
поверх первичных клипс перед обмоткой как
показано выше.



100 mm
overlap


100 мм
обмотка

первая внешняя защитная
сleeve
First outer protection
sleeve



Shrink end to
centre

натянуть конец к центру



- Attached 3 short lengths of copper braid to the cable armour using a roll spring. Over tape roll spring with EPR Tape.
- Connect the copper earth wires and the copper braid together using a tunnel connector.
- Bind the earth wires and joint bodies together using a binding of 24 tape, tinned copper bandage around the centre of the joint.
- Wrap the earth cage around the joint and secure to the armours using the worm-drive clips, (over-tape clips with EPR tape).
- Slide the first outer protection sleeve over the joint overlapping the sheath by 100 mm.
- Shrink the sleeve into place starting at the sheath and working towards the centre.
- Slide the second outer protection sleeve over the joint overlapping the sheath by 100 mm.
- Shrink the sleeve into place starting at the sheath and working towards the sheath.